

Project: Alaska Copper Works				Inspection Date:			02/12/2019	
Project No.: 19ACW1				Technician:			David Carrico	
System Performan	nce:							
Was system running	g during the i	nspection?	☐ Yes	□ No				
Flow Rates (gpm)		Influent _	153	Effluent _	148	The flows sh	ould be ~1	.55 gpm
Bag Filter #1 Pressures (psi)		Influent _	16	Effluent _	12	The bag filte		•
Bag Filter #2 Pressu	res (psi)	Influent _	16	Effluent _	11	n umerenda	ii pressure	> 0 hai
Carbon Filter Pressu	ıres (Lead)	Influent _	10	Effluent _	6	The carbon		
Carbon Filter Pressu	res (Lag)	Influent _	5	Effluent _	0	pressure > 8		uai Ala Ala
Were the bag filters	replaced?	☐ Yes 🗵	No					
Was the carbon bac	kflushed?	□ Yes 🗵	No					

## **Maintenance and Inspection Checklist:**

Task	Completed (Y/N)	Issues/Notes/Comments
Walchem Controller Inspected	⊠ Yes □ No	
Flow Meters Inspected	⊠ Yes □ No	
Level Sensor Cleaning/Inspection	☐ Yes ⊠ No	
Inspect System Plumbing	⊠ Yes □ No	
Pumps Inspected	⊠ Yes □ No	
General Housekeeping	☑ Yes ☐ No	
Chemistry Level	☑ Yes ☐ No	2 full barrels
Safety Materials Inspected	☑ Yes ☐ No	
pH Probe Inspection/Calibration	□ Yes 🗵 No	New probe will be installed on 2/20/2019



Water Sampling:						
Were water samples tal	ken? 🛛 Yes	□ No				
Raw water:	pH7.63	Turbidity _	22.5	NTU		
Bag Filter Influent	pH 8.12	Turbidity _	13.5	NTU		
Bag Filter Effluent	pH	Turbidity	11.9	NTU		
Carbon Filter Influent	pH	Turbidity _	8.9	NTU		
Carbon Filter Effluent	pH 7.31	Turbidity _	5.3	NTU		
Monthly Tasks:						
Were samples submitte	d to Analytical?	☐ Yes 区 N	0			
Analytical Lab:		_				
Was Walchem data downloaded?		□ Yes 図 No	D			
Were the tank sludge levels checked?		□ Yes ⊠ No	<b>o</b>			
Sludge Depth (inches):						
Decant Tank:						
Treatment tank:	·····					
Backflush tank:						
Main lift station:						
North lift station:						
South lift station:	un-eurome					
Additional Comments, I	Recommendatio	ons and Syste	m Upse	ts:		
David Carrico	)	Field	Tech		02/12/2019	
Technician		Tit	le		Date	

Submit
Page 2 of 2